

APPENDIX A

Bridge Photographs

Bridge Photographs



Photograph 1. A general view of the bridge looking toward the southwest




Photograph 2. The operator's house at the east end of the bridge

STRUCTURAL SYSTEM INSPECTION PHOTOGRAPHS

BRIDGE: FORT STREET BRIDGE (STRUCTURE ID NO. 82 1820710000000B04) DATE: OCTOBER 1998




PHOTOGRAPH S-11 - View showing typical corrosion between back-to-back angles of floorbeam lower struts and reduced horizontal flange angle legs.



PHOTOGRAPH S-12 - View showing loss of floorbeam lower strut fastener due to occasionally occurring pack rust at inboard truss upper connection plates.

Photographs 3 (S-11) and 4 (S-12). Structural Inspection Photographs



Photograph 5. View of bridge fender system, northeast quadrant



Photograph 6. View of the Oakwood Boulevard/South Fort Street intersection

